



(महारत्न कंपनी)

# COAL INDIA LIMITED

(Govt. of India Enterprise)  
Premises No.04, MAR, Plot no.AF-III  
Action Area 1A, New Town, Rajarhat,  
KOLKATA - 700 156  
CIN : L23109WB1973GOI028844

No.CIL/CH/Secy/36(A)/416  
30.12.2016

## OFFICE MEMORANDUM

Sub: **Constitution of High Powered Committee in respect of accident which occurred at Rajmahal OCP, ECL on 29.12.2016**

1. In the context of accident that occurred at Rajmahal OCP of ECL on 29.12.2016 a High Powered Committee consisting of the following members is hereby constituted to carry out in-depth examination of the accident :

- |  |   |                     |
|--|---|---------------------|
| a. Shri Shekhar Saran, CMD, CMPDIL,                    | : | Chairman            |
| b. Shri P.K. Sinha, Director(Tech/P&P), SECL           | : | Member              |
| c. Dr. Phalguni Sen, Professor, IIT(ISM),              | : | Member              |
| d. Dr. V.K. Singh, Head of Slope Stability Divn, CIMFR | : | Member              |
| e. Prof. I. Roy, BIT, Mesra                            | : | Member              |
| f. Shri A.K. Nath, GM/TS to DT, CIL                    | : | Member<br>Secretary |

2. The committee will examine the following aspects :

- i) The cause of the accident
- ii) Human failure, if any,
- iii) Whether the accident could have been avoided by taking identified corrective measures.
- iv) Measures to avoid recurrence of such accidents in future in Rajmahal OCP and other OC mines of CIL with similar workings.

3. The committee shall submit its report within One month.

  
(Sutirtha Bhattacharya)  
Chairman

Dist:

All Committee Members

Copy for kind information :

- 1) The Director(T), CIL
- 2) The CMD, SECL
- 3) The CMD, ECL
- 4) The Director, ISM/IIT
- 5) The Director, CIMFR
- 6) The Vice Chancellor, BIT, Mesra